





1000 S Winchester Blvd San Jose, CA 95128 P: (408) 998 - 0983

F: (408) 404 - 0144

 $\geq |\geq |\geq |\geq$

COVER SHEET





1 2 4 6 8 feet

Section	Dimensions(X x Y)	Area (sf)
New Floor Living Area	· · · · · · · · · · · · · · · · · · ·	
L1	14'-6" x 28'-5 1/2"	412.65
L2	6'-3" x 24'-2 1/2"	151.35
L3	14'-6" x 28'-5 1/2"	412.65
L4	12'-1 1/2" x 26'-7"	322.32
L5	4'-3 1/2" x 24'-3 1/2"	104.25
L6	3'-10" x 17'-5"	67.49
L7	17'-2" x 21'-1"	361.95
L8	14'-0 1/2" x 20'-4"	285.54
L9	13'-3 1/2" x 12'-2 1/2"	162.43
L10	21'-2 1/2' x 49'-8 1/2"	1,054.51
L11	3'-10 1/2" x 49'-10 1/2"	193.32
Total		3,528.46


New Garage Area		
G1	4'-3 1/2" x 2'-3 1/2"	9.83
G2	20'-5 1/2" x 20'-4"	415.99
Total		425.82

New Porch/Patio Area		
P1	1'-4" x 4'-11 1/2"	6.70
P2	9'-8 1/2" x 4'-11 1/2"	48.05
P3	1'-4" x 4'-11 1/2"	6.70
P4	12'-5" X 1'-9"	21.73
P5	6'-3" × 4'-3"	26.57
P6	17'-2 1/2" x 11'-5 1/2"	197.39
P7	30'-6" x 12'-5 1/2"	380.01
P8	4'-1 1/2" x 18'-6"	76.18
Total		763.33


New Trellis Area (LC exception)		
T1	28'-9'' x 7'-6''	215.70
T Total		215.70

New Hardscape Area	
H1 (front yard area)	247.87
H2	76.69
Н3	89.83
H4 (driveway)	402.50
H5 (rear yard)	189.00
Total	1,005.89


LA	<u>Lot Area</u>	12,054.00	
G	Total New Garage Area	425.82	
FAR=L+G	Total New Residence	3,954.28	
	Floor Area Ratio Max.	3,955.40	
FAR/LA	FAR Percentage	32.80%	
	Lot Coverage Max.	4,218.90	
LC=FL+G+P2	Proposed Lot Coverage	4,178.24	
LC/LA	Lot Coverage Percentage	34.66%	<35% (OK
LA*0.05	LC exception for trellis structures max	602.70	5%
Т	Trellis Area	215.70	
	LC exception percentage	1. 79 %	<5% (OK)
NH=H=+P	New Hardscape Area	1,769.22	
TH=NH+FL	Total Hardscape Area	5,297.68	
FS	Front Yard Setback Area	2,001.10	
H=H1+{P1:P4}	Front Yard Hardscape Area	331.05	
R=SH/FS	Front Yard Hardscape Area Ratio	16.54%	<50% (OK



NL# = NEW LIVING AREA



NG# = NEW GARAGE AREA



NP# = NEW PORCH AREA




FLOOR AREA CALCS 3/16"



H# = NEW HARDSCAPED AREA

FLOOR AREA LEGEND




ARCHITECTURE 1000 S Winchester Blvd San Jose, CA 95128 P: (408) 998 - 0983 F: (408) 404 - 0144

RESIDENCE
Y RESIDENCE 137 SYLVIAN WAY, LOS ALTOS

ZHENG-ZHONG
NEW SINGLE FAMILY



FLOOR AREA CALCULATION SHEET










ARCHITECTURE

1000 S. Winchester Blvd San Jose, CA 95128 P: (408) 998 - 0983

F : (408) 404 - 0144

137 SYLVIAN WAY, LOS ALTOS


RESIDENC



ROJECT NO.			21
REVISION	DATE	DESCRIPTION	DRAWN BY
	2018.06.20.	PLANNIG PERMIT SUBMITTAL	<u>></u>
	2018.09.12.	PLANNIG PERMIT RESUBMITTAL	2
	2018.11.01.	DRC SUBMITTAL SET	2
	2018.11.30.	DRC SUBMITTAL SET	2

PROJECT NO.			
REVISION	DATE	DESCRIPTION	DRAV
	2018.06.20.	PLANNIG PERMIT SUBMITTAL	2
	2018.09.12.	PLANNIG PERMIT RESUBMITTAL	>
	2018.11.01.	DRC SUBMITTAL SET	2
	2018.11.30.	DRC SUBMITTAL SET	≥

DAYLIGHT PLANE



REAR LEFT HIGH VIEW

3

NO DAYLIGHT PLANE PROTRUSIONS

NO DAYLIGHT PLANE PROTRUSIONS

REAR RIGHT HIGH VIEW -

FRONT LEFT HIGH VIEW -


















151 CHERRY AVE 282 CHERRY AVE 136 SYLVIAN WAY




324 CHERRY AVE





MAP -





STREETSCAPES







1000 S Winchester Blvd San Jose, CA 95128 P: (408) 998 - 0983

P: (408) 998 - 0983 F: (408) 404 - 0144

RESIDENCE RESIDENCE

NEW SINGLE FAMILY RESIDENCE

137 SYLVIAN WAY, LOS ALTOS

ARCHITECON ARCHITECON ARCALIFORM ARCHITECON ARCHITECON

PROJECT NO.

REVISION DATE DESCRIPTION


2018.06.20. PLANNING PERMIT SUBMITTAL


2018.09.12. PLANNING PERMIT RESUBMITT

2018.11.01. DRC SUBMITTAL SET

2018.11.30. DRC SUBMITTAL SET

SITE PLAN & DEMO SITE PLAN







1000 S Winchester Blvd San Jose, CA 95128 P: (408) 998 - 0983

P: (408) 998 - 0983 F: (408) 404 - 0144

ONG RESIDENCE

NEW SINGLE FAMILY RESIDENCE


137 SYLVIAN WAY, LOS ALTOS


C27,719 IED ARCHITECT



PROJECT NO.		
REVISION	DATE	DESCRIPTION
	2018.06.20.	2018.06.20. PLANNING PERMIT SUBMITTA
	2018.09.12.	2018.09.12. PLANNING PERMIT RESUBMI
	2018.11.01.	2018.11.01. DRC SUBMITTAL SET
	2018.11.30.	2018.11.30. DRC SUBMITTAL SET

FLOOR PLAN





- 1. (N) ROOFING--SEE LEGEND BELOW FOR MATERIALS--CONFIRM COLOR SELECTION W/ OWNER PRIOR TO PLACING ORDER
- 2. PAINT ALL ROOF PENETRATIONS TO MATCH ROOFING COLOR.
- 3. RUN PLUMBING/HVAC VENTS TO FALSE CHIMNEY PROVIDED. NO ROOF PENETRATIONS THROUGH ROOF. PLUMBING VENTS TO BE MIN. 10' AWAY FROM, OR AT LEAST 3' ABOVE ANY OPERABLE WINDOW OR SKYLIGHT PER CPC 906.2. RUN TO FALSE CHIMNEYS
- 5. PROVIDE (N) GSM ROOF JACKS, TYP. CAULK ALL EXPOSED NAIL HEADS WITH SILICONE SEALANT.
- 6. PROVIDE (N) GUTTERS AND DOWNSPOUTS AT LOCATIONS SHOWN
- 7. ALL (N) PLATE HEIGHTS PER SECTIONS AND RCP. SEE STRUCTURAL DRAWINGS FOR ADDITIONAL INFORMATION.
- 8. CONNECT ALL (N) DOWNSPOUTS TO FLEXIBLE PLASTIC DRAINPIPE AND RUN TO A LOCATION SPECIFIED BY CIVIL PLANS
- 1. SEE 2/A0.1a FOR PLUMBING GENERAL NOTES
- 2. SEE 3/A0.1a FOR MECHANICAL GENERAL NOTES
- 3. SEE 4/A0.1a FOR ELECTRICAL GENERAL NOTES
- 4. SEE 5/A0.1a FOR PLAN AND INTERIOR GENERAL NOTES

ROOF GENERAL NOTES



1000 S Winchester Blvd San Jose, CA 95128

P: (408) 998 - 0983

F: (408) 404 - 0144

RESIDENCE ALTOS

SYLVIAN 137



ATTIC VENTILATION CALCULATIONS AND NOTES

STANDING SEAM METAL ROOF, MIN CLASS C--MANUF: AEP SPAN; STYLE: DESIGN SPAN - DURA TECH; COVERAGE: 16"; GAUGE: 22; COLOR: COOL MATE BLACK--VERIFY FINAL SELECTION WITH OWNER PRIOR TO PLACING ORDER. INSTALL PER MANUF. WARRANTY INSTRUCTIONS AND [UES EVALUATION REPORT #0309]

DENOTES GUTTER DRAIN (3" DIA.) AND DOWNSPOUT (2" X 3") 26 GA ALUMINUM - FIELD VERIFY COLOR W/ OWNER. INSTALL PER MFR. INSTRUCTIONS

DENOTES DIRECTION OF SLOPE--ROOF SLOPE APPROX., REFER TO ELEVATIONS FOR MAX HT AND VERTICAL CONTROL

---- LINE OF BLDG. BELOW

ROOF PLAN LEGEND

ROOF PLAN





1000 S. Winchester Blvd San Jose, CA 95128


P: (408) 998 - 0983 F: (408) 404 - 0144


ESIDEN

SYLVIAN 137

HENG

EXTERIOR **ELEVATIONS**








1000 S. Winchester Blvd San Jose, CA 95128 P: (408) 998 - 0983


F: (408) 404 - 0144

ESIDEN


SYLVIAN 137

EXTERIOR **ELEVATIONS**

















MAP AND EXISTING EXTERIOR SIDE ELEVATIONS





EXISTING ELEVATIONS







PERSPECTIVE EXTERIOR FRONT


PERSPECTIVE EXTERIOR LEFT





	PROJECT NO.		
F	REVISION	DATE	DESCRIP
=X		2018.06.20.	PLANN
TE		2018.09.12.	PLANN
-R		2018.11.01.	DRC SI
IC		2018.11.30.	DRC SI
)R			
1			

PERSPECTIVES



PERSPECTIVE EXTERIOR FRONT HIGH (CORNER)

PERSPECTIVE EXTERIOR FRONT RIGHT -







PERSPECTIVE EXTERIOR LEFT REAR






PERSPECTIVE EXTERIOR RIGHT REAR

PERSPECTIVE EXTERIOR REAR




EXTERIOR PERSPECTIVES



PERSPECTIVE EXTERIOR MASTER BEDROOM DOORS

PERSPECTIVE EXTERIOR PATIO


ARCHITECTURE






1000 S. Winchester Blvd


F : (408) 404 - 0144





EXTERIOR PERSPECTIVES AND DETAILS





ZHONG RESIDENC CONSTRUCTION ZHENG "FOR PLANNING APPROVAL


ARCHITECTURE

1000 S. Winchester Blvd

137 SYLVIAN WAY, LOS ALTOS

17-015	DRAWN BY	\ \	>	2	2	
	DESCRIPTION	PLANNIG PERMIT SUBMITTAL	PLANNIG PERMIT RESUBMITTAL	DRC SUBMITTAL SET	DRC SUBMITTAL SET	
		06.20.	39.12.	11.01.	11.30.	

SECTIONS



WOOD CLAD WINDOW UNIT WITH
WOOD CLAD WINDOW UNIT WITH INSUL. GLAZING - INSTALL PER MFR INSTRUCT.
PAINTED METAL FLASHING SELF- ADHERING FLASHING
1x INTERIOR WOOD/MDF TRIM AND
APRONVERIFY PROFILE WITH OWNER
WOOD FRAMING PER STRUCTURAL DRAWINGS
GALVANIZED SHEET METAL FLASHING
PLASTER J MOLD @ PLASTER WALLS
2X SHAPED TRIM (SILL) @ LOCATIONS SHOWN ON ELEVATIONSSEE
ELEVATIONS FOR MORE INFO
2 LAYERS GRADE 'D' BUILDING PAPER
EXTERIOR FINISH ASSEMBLYSEE ELEVATIONS FOR MORE INFO
5/8" GYP. BD.
NOTE: REFER TO MANUFACTURERS INSTRUCTIONS FOR SEALANT REQUIREMENTS
TYPICAL WINDOW SILL 3" 1
=
STRICE OF THE PROPERTY OF THE
ŭ
>
C
('
Ž
er_\Delai\
直




1000 S Winchester Blvd San Jose, CA 95128 P: (408) 998 - 0983 F: (408) 404 - 0144


ZHENG-ZHONG RESIDENCE NEW SINGLE FAMILY RESIDENCE


137 SYLVIAN WAY, LOS ALTOS





DETAILS





ZHONG RESIDENCE

137 SYLVIAN WAY LOS ALTOS, CA APN: 167-29-034

WEC & ASSOCIATES



LICENSE STAMPS AND SIGNATURE




No.	Description	Date
DAT	E: JUNE 6, 2017	
SCA	1/8"=1'-0"	
DRA	BG	
JOB:	10078	

TOPOGRAPHIC SURVEY

SHEET NO.

C.(



415 894 0511 eve@seed-studio.net seed-studio.net

RESIDENCE


ZHONG

137 SYLVIAN WAY ZHENGALTOS, CALIFORNIA

JANUARY 22, 2019 LANDSCAPE

L1.0

ZHENG-ZHONG RESIDENCE						
SYM	SCIENTIFIC NAME	COMMON NAME	SIZE	HEIGHT		
TRE	EES					
Α	Alnus rhombifolia	White Alder	24" BOX	50'		
В	Prunus ilicifolia ssp. lyonii	Catalina Cherry	24" BOX	30'		
С	Acer circinatum	Vine Maple	24" BOX	15'		
D	Cercis occidentalis	Western Redbud	24" BOX	20'		
SHI	RUBS / PERENNIALS					
1	Frangula californica	Coffeeberry	5 GAL	10'		
2	Holodiscus discolor	Cream Bush	5 GAL			
3	Ribes sanguineum var. glutinosum	Red Flowering Currant	5 GAL			
4	Philadelphus lewisii	Wild Mock Orange	5 GAL	10'		
5	Woodwardia fimbriata	Giant Chain Fern	5 GAL	4'		
6	Festuca californica	California Fescue	1 GAL			
7	Heuchera micrantha	Crevice Alum Root	1 GAL			
8	Iris douglasiana	Douglas Iris	1 GAL			
10	Frangula californica 'Mound San Bruno'	Coffeeberry	5 GAL	6'		
11	Muhlenbergia rigens	Deer Grass	1 GAL	3'		
12	Ribes viburnifolium	Catalina Currant	1 GAL	3'		
13	Achillea millefolium	Common Yarrow	1 GAL			
14	Asclepias speciosa	Showy Milkweed	1 GAL			
15	Salvia spathacea	Hummingbird Sage	1 GAL			
GR	OUNDCOVERS					
G1	Symphoricarpos mollis	Creeping Snowberry	1 GAL			
G2	Mentha requienii	Corsican Mint	FLATS			
G4	Deschampsia cespitosa	Tufted Hair Grass	1 GAL			
TUŀ	RF					
	Native No-Mow Blend, Delta Bluegrass Co. (ROLLS				
TRA	ANSPLANTS					
T1	Acer palmatum	Japanese Maple	-			
T2	Acer palmatum	Japanese Maple	-			
Т3	Acer palmatum	Japanese Maple	-			



SCALE: 1/8" = 1'-0"

NOTE

SEE SHEET L1.5 FOR NOTES / DETAILS

June 20, 2018

Hua Zhong and Jessie Zheng hzhong@gmail.com jessie.sourire@gmail.com

Site: 137 Sylvian Way, Los Altos

Dear Hua Zhong and Jessie Zheng,

As requested on Friday, February 16, 2018, I visited the above site for the purpose of inspecting and commenting on the trees. A new home is planned for this site and your concern as to the future health and safety of existing trees has prompted this visit. Site plan A1.0 dated 6/20/18 was used for this report.

All inspections were made from the ground; the trees were not climbed for this inspection. The trees in question were located on an existing topography map provided by you. The trees were then measured for diameter at 54 inches above ground level (DBH or diameter at breast height). The trees were given a condition rating for form and vitality. Each tree was put into a health class using the following rating system:

> **F-** Very Poor **D-** Poor C- Fair B- Good A- Excellent

The height of the trees was measured using a Nikon Forestry 550 Hypsometer. The spread was paced off. Comments and recommendations for future maintenance are provided.

137 Sylvian Way /6/20/18

DBH CON HT/SP Comments 16.6 F 35/20 Poor vigor, poor form, large areas of dead 1P Camphor wood, sun scald, in decline, street tree. (Cinnamomum camphora) 2P Camphor 21.9 C 35/30 Fair vigor, fair to poor form, pruned for

(Cinnamomum camphora) utilities, dead wood in canopy, street tree. 19.0 C 30/25 Fair vigor, fair to poor form, pruned for 3P Camphor (Cinnamomum camphora) utilities, dead wood in canopy, street tree.

4P Camphor 14.5 C 30/30 Fair vigor, fair to poor form, pruned for (Cinnamomum camphora) utilities, dead wood in canopy, street tree. 13.7 C 30/25 Fair vigor, fair form, minor dead wood in 5P Camphor

(Cinnamomum camphora) canopy, street tree. 6P Crape myrtle 8.1 C 15/8 Fair vigor, poor form, suppressed by #5, (Lagerstroemia spp.) street tree.

7R Japanese maple 4.0 B 8/8 Fair vigor, fair form. Proposed for tree removal (Acer palmatum)

8 Saucer magnolia 5.1 B 10/15 Good vigor, good form, close to home. (Magnolia soulangeana)

9P Japanese maple 3.1 C 6/5 Fair vigor, poor form, decay at base. (Acer palmatum)

(Olea europaea) 11**P** Olive 8"x3 B 20/15 Fair vigor, fair form, multi leader at grade.

9"x3 B 20/15 Fair vigor, fair form, multi leader at grade.

(Olea europaea) 7"x3 B 20/12 Fair vigor, fair form, multi leader at grade, 12**P** Olive (Olea europaea)

13**P** Olive 7.0 C 15/12 Fair vigor, fair form, multi leader at grade, (Olea europaea)

14 Star magnolia 4.0 B 15/8 Food vigor, fair form, suppressed. (Magnolia stellata)

137 Sylvian Way /6/20/18

(Acer spp.)

Survey: Tree# Species DBH CON HT/SP Comments 8.0 C 20/10 Fair vigor, poor form, suppressed by ivy. 15 Olive (Olea europaea)

16 Olive 8.0 C 20/10 Fair vigor, poor form, suppressed by ivy. (Olea europaea) 9.5 B 30/30 Fair vigor, fair form, missile toe in canopy. 17 Acer

9.1 B 15/12 Fair vigor, fair form/ 18 Japanese maple (Acer palmatum)

11.3 B 15/15 Fair vigor, fair form, sun scald. 19 Japanese maple (Acer palmatum) 6.7 C 15/12 Fair vigor, poor form, codominant at grade. 20 Japanese maple

(Acer palmatum) 21* Privet 10est C 25/15 Fair vigor, poor form, codominant at grade.

(Ligustrum japonicum) 13est C 30/15 Fair vigor, fair form, codominant at grade. (Ligustrum japonicum)

23**R** Japanese maple 8.0 B 20/20 Fair vigor, fair form. (Acer palmatum) Proposed for removal

24 Crape myrtle 9.6 D 20/10 Fair vigor, poor form, topped, multi leader at (Lagerstroemia spp.)

25R Japanese maple 14.1-13.6 C 25/25 Fair vigor, fair form, codominant at one

(Acer palmatum) foot, sun scald. Proposed for removal 14est C 30/12 Fair to poor vigor, poor form, abundance of 26* Privet (Ligustrum japonicum)

27 Japanese maple 9.1 B 20/20 Good vigor, good form. (Acer palmatum)

28* Privet 13est C 30/20 Fair to poor vigor, poor form, codominant at (Ligustrum japonicum) grade, dead wood.

137 Sylvian Way /6/20/18

Tree# Species **DBH CON HT/SP Comments** 20est C 30/20 Fair to poor vigor, fair form, pruned for 29*P Camphor (Cinnamomum camphora) utilities, abundance of dead wood.

30 Crape myrtle 8.1 C 25/12 Fair vigor, poor form, codominant at grade, (Lagerstroemia spp.)

P-*Indicates protected tree by city ordinance* R-Indicates proposed tree removal

*-Indicates neighbors tree

Site observations:

The landscape at 137 Sylvian Way has been well maintained in the past. The site is heavily planted, and has an aesthetically pleasing landscape. Because this site is on a corner lot, it has a large area for street tree plantings. Eleven trees are located in the public right of way and are considered to be protected trees.

Trees #7, #23 and #25 are the only trees on site proposed for removal in order to facilitate the proposed construction. These trees are not of a protected size in Los Altos.

Protected trees on site:



Camphor tree #1-5 and #29 are in fair condition with the exception of camphor tree #1 in poor condition. Tree number 1 was given a F condition rating as it is nearly dead. This tree is recommended for removal. Because 11 street trees surround the property a new street tree should not be required as there is not enough room for a new street tree.

Showing tree #1 nearly dead

137 Sylvian Way /6/20/18

Camphor trees #1-5 and #29 are located along Sylvian Way in the public right of way. Areas of die back were observed in the tree canopies. These trees are below overhead utilities and need to be pruned for line clearance. Also, past street work may have impacted the roots of these trees. It is recommended to irrigate these trees in the dry months as the decline in vigor could be due to drought stress. These trees are required to be protected as they are street trees. A new walkway between camphor trees #1 and #2 is proposed. Because tree #1 is nearly dead this tree should be removed before the start of construction. This walkway must be excavated by hand leaving all encountered roots exposed and damage free when under the dripline of the trees. The project arborist shall be called to the site to witness the manual excavation by hand when underneath the dripline of the tree in order for proper documentation to take place. It is the contractors responsibility to contact the project arborist in a timely manner. No roots shall be cut in the required base rock area. Structural Soil (CU Mix) shall be used as a base rock material when underneath the tree driplines, as Structural Soil can be packed around tree roots and compacted to engineering standards, while still allowing for future root growth. The pathway shall be constructed as close as possible to on top of grade. Impacts for the walkway are expected to be

Crape myrtle tree #6 and Japanese maple tree #9 are both small protected trees located in the public right of way. These trees were likely planted by the past homeowner. Both trees are to be retained and no impacts are expected if tree protection is installed at the trees driplines.

minor. Mitigations for the camphor trees will consist of heavy dry season irrigation.

Olive trees #9-13 are protected trees located in the public right of way. These trees are to be retained and protected throughout the entire length of construction. No impacts are expected for these trees. The following tree protection plan will help insure the health of the existing trees to be retained. Even though some of the trees are not protected, they are recommended to be protected by tree protection fencing if retained for the project.

Tree Protection Plan: Tree Protection Zones

Tree protection zones should be installed and maintained throughout the entire length of the project. Fencing for tree protection zones should be 6' tall, metal chain link material supported by metal 2" diameter poles, pounded into the ground to a depth of no less than 2'. The location for the protective fencing for the protected trees on site should be installed no closer to the trunk than the dripline (canopy spread) in order to protect the integrity of the tree. The location of the tree protection fencing may be modified by the planning director. When it is not possible to place tree protection fencing at the dripline because of the proposed work or existing hardscapes, the tree protection fencing shall be placed at the edge of the proposed work or hardscapes. No equipment or materials shall be stored or cleaned inside the protection zones. Areas where tree protection fencing needs to be reduced for access, should be mulched with 6" of coarse wood chips with ½ inch plywood on top. The plywood boards should be attached together in order to minimize movement. The spreading of chips will help to reduce compaction and improve soil structure. All tree protection measures must be installed prior to any demolition or construction activity at the site. The non-protected trees are recommended to be protected in the same manner as the protected trees on site. No signs, wires, or any other object shall be attached to the trees.

137 Sylvian Way /6/20/18 If impacts are expected to any of the trees on site, proper mitigation measures will need to be put into action to reduce overall impacts to the trees.

Landscape Buffer

10**P** Olive

Where tree protection does not cover the entire root zone of the trees, or when a smaller tree protection zone is needed for access, a landscape buffer consisting of wood chips spread to a depth of six inches with plywood or steel plates placed on top will be placed where foot traffic is expected to be heavy. The landscape buffer will help to reduce compaction to the unprotected

Root Cutting and Grading

Any roots to be cut shall be monitored and documented. Large roots (over 2" diameter) or large masses of roots to be cut must be inspected by the site arborist. The site arborist, at this time, may recommend irrigation or fertilization of the root zone. All roots needing to be cut should be cut clean with a saw or lopper. Roots to be left exposed for a period of time should be covered with layers of burlap and kept moist. The existing grade level around the trees shall be maintained out to the dripline of the trees. Alternate grade levels may be approved with special mitigation measures put in place.

Trenching and Excavation

Trenching for irrigation, drainage, electrical or any other reason shall be done by hand when inside the dripline of a protected tree. Hand digging and the careful placement of pipes below or besides protected roots will significantly reduce root loss, thus reducing trauma to the tree. All trenches shall be backfilled with native materials and compacted to near its original level, as soon as possible. Trenches to be left open for a period of time, will require the covering of all exposed roots with burlap and be kept moist. The trenches will also need to be covered with plywood to help protect the exposed roots.

Imported trees- On a construction site, I recommend irrigation during winter months, 1 time per month. Seasonal rainfall may reduce the need for additional irrigation. During the warm season, April – November, my recommendation is to use heavy irrigation, 2 times per month. This type of irrigation should be started prior to any excavation. The irrigation will improve the vigor and water content of the trees. The on-site arborist may make adjustments to the irrigation recommendations as needed. The foliage of the trees may need cleaning if dust levels are extreme. Removing dust from the foliage will help to reduce mite and insect infestation.

principles and practices.

Sincerely, Kevin Kielty Certified Arborist WE#0476A

It is the contractor's responsibility to contact the site arborist when work is to take place underneath the canopy or dripline of a protected tree on site. Kielty Arborist Services can be reached by email at kkarbor0476@yahoo.com or by phone at (650) 515-9783 (Kevin) or (650) 532-4418 (David). The information included in this report is believed to be true and based on sound arboricultural

CHERRY AVENUE

RESIDENCE WEC THE FACE OF STUCCO OR SERVICE To Da

ARCHITECTURE


1000 S Winchester Blvd San Jose, CA 95128

P: (408) 998 - 0983 F: (408) 404 - 0144

ALTOS ESIDENCE SIDENCE COS

WAY, -ZHONG SINGLE FAMILY SYLVIAN EN SHAN ESSII 37

RU



(C) STUDIO S SQUARED ARCHITECTURE, INC