


Legend:

- = Existing sidewalk
- = No sidewalks & shoulder difficult to walk on
- = Unpaved shoulder to walk on the side of the roadway



At the Covington/Miramonte intersection, the following queues were observed:

| Approach | AM | PM |
|------------|-----|----|
| Northbound | 21+ | 4 |
| Southbound | 20+ | 8 |
| Eastbound | 41+ | 3 |
| Westbound | 15+ | 3 |

City of Los Altos
Blach School Neighborhood
Traffic Study
December 2010